- Case Study:
 - New 5 Level ParkingStructure
 - Improper Concrete Pour
- Issues:
 - Wavy Beams
 - Non-compliant Heights
 - Conc. Sub Bankrupt
 - How to quickly identify trouble areas?









Solution: Laser Scan





































Results

- Reduced assessment time by 80%
- Significantly more measured points
- Higher confidence
- Pinpoint and focus only on trouble areas
- Faster resolution







Truss Analysis

